

# Technical Service Bulletin



Of Interest ☐ General Manager ☐ Sales Manager ☐ Service Manager ☐ Parts Manager ☐ Service Technicians

May 6, 1971

No. D71-8-9

A running change will be made during the 1971 Model year to incorporate an Electronic Ignition System into the subject models when equipped with the 340 C.I.D. engine and manual transmission.

Engines with the Electronic Ignition System can be easily identified. The distributor will have a double primary wire. The ballast resistor will be of dual type and a control unit will be mounted on either the dash or fender shield. Figure 1 shows the Chrysler system.

ELECTRICAL

Chrysler  
Electronic  
Ignition  
System




FIGURE 1 CHRYSLER ELECTRONIC IGNITION SYSTEM

(Over)

MODELS:  
Dart,  
Challenger  
And Charger  
Equipped With  
340 C.I.D.  
Engine And  
Manual  
Transmission  
P-1306

(THIS BULLETIN IS SUPPLIED AS TECHNICAL INFORMATION ONLY AND IS NOT AN AUTHORIZATION FOR REPAIRS)  
REPRINT OF THIS MATERIAL NOT AUTHORIZED UNLESS APPROVED BY MANAGER OF SERVICE, DODGE DIVISION



COLT/CHALLENGER/CHARGER/CORONET/DART/MONACO/POLARA



The Chrysler Electronic Ignition System is composed of a magnetic distributor, an electronic control unit, a wiring harness, a production coil and a dual ballast resistor. See Figure 2.




FIGURE 2 ELECTRONIC IGNITION SYSTEM COMPONENTS

The distributor is essentially the same as the conventional distributor except the contacts have been replaced by a pickup coil and the cam by a reluctor. Figure 3 shows the reluctor, pickup coil and control unit.




FIGURE 3 MAGNETIC PICKUP COMPONENT AND CONTROL UNIT



With a conventional contact type ignition system, the voltage necessary to fire the spark plugs is developed by interrupting the current flowing through the primary of the ignition coil by opening a set of contacts. With the Electronic Ignition System, the voltage is produced the same way except that the current is interrupted by a transistor in the electronic control unit. This happens each time the control unit receives a "timing" pulse from the distributor magnetic pickup.

Since the magnetic pickup, reluctor and the control unit, which replace the contact points and cam, do not normally change or wear out with service, engine timing and dwell does not require periodic adjusting. This minimizes regular ignition maintenance to cleaning and replacing spark plugs.

### ELECTRONIC IGNITION SYSTEM SERVICE DIAGNOSIS

| <u>CONDITION</u>  | <u>POSSIBLE CAUSE</u>                             | <u>CORRECTION</u>   |
|---|---|---|
| ENGINE<br>WILL NOT<br>START<br>(Fuel and<br>Carburetion<br>Known to be<br>O.K.) | a) Dual Ballast                                   | Check resistance of each section:<br>Compensating resistance:<br>.50-.60 ohms 70°-80°F<br>Auxiliary Ballast: 4.75-5.75 ohms<br>Replace if faulty. Check wire positions.   |
|   | b) Faulty Ignition<br>Coil                        | Check for carbonized tower. Check<br>primary and secondary resistances:<br>Primary: 1.41-1.79 ohms 70°-80°F<br>Secondary: 9200-11700 ohms 70°-80°F<br>Check in coil testor.   |
|   | c) Faulty Pickup<br>or Improper<br>Pickup Air Gap | Check pickup coil resistance:<br>400-600 ohms<br>Check pickup gap: .010" feeler gauge<br>should not slip between pickup coil<br>core and an aligned reluctor blade.<br>No evidence of pickup core striking<br>reluctor blades should be visible. To<br>reset gap, tighten pickup adjustment<br>screw with .008" feeler gauge held be-<br>tween pickup core and an aligned re-<br>luctor blade. After resetting gap,<br>run distributor on test stand and<br>apply vacuum advance, making sure that<br>the pickup core does not strike the<br>reluctor blades. |
|   | d) Faulty Wiring                                  | Visibly inspect wiring for brittle in-<br>sulation. Inspect connectors. Molded<br>connectors should be inspected for<br>rubber inside female terminals.   |
|   | e) Faulty Control<br>Unit                         | Replace if all of the above checks are<br>negative. Whenever the control unit or<br>dual ballast is replaced, make sure the<br>dual ballast wires are correctly in-<br>serted in the keyed molded connector.  |



ELECTRONIC IGNITION SYSTEM SERVICE DIAGNOSIS (CONTINUED)

| <u>CONDITION</u>                             | <u>POSSIBLE CAUSE</u>  | <u>CORRECTION</u>  |
|--|------------------------|--|
| ENGINE SURGES SEVERELY (Not Lean Carburetor) | a) Wiring              | Inspect for loose connection and/or broken conductors in harness.                                      |
| ENGINE MISSES (Carburetion Known Good)       | b) Faulty Pickup Leads | Disconnect vacuum advance. If surging stops, replace pickup.   |
|  | c) Ignition Coil       | Check for intermittent primary.  |
|  | a) Spark Plugs         | Check plugs. Clean and regap if necessary.   |
|  | b) Secondary Cables    | Check cables with an ohmmeter, or observe secondary circuit performance with an ignition oscilloscope. |
|  | c) Ignition Coil       | Check for carbonized tower. Check in coil tester.  |
|  | d) Wiring              | Check for loose or dirty connections.  |
|  | e) Control Unit        | Replace if the above checks are negative.  |

ELECTRONIC IGNITION SYSTEM SPECIFICATION

|  |   |
|--|---|
| Engine Displacement  | 340 C.I.D. W/Man. Trans.  |
| Distributor Part No. (Chrysler Built Electronic)             | 3656151   |
| Advance-Centrifugal (Distributor Degrees at Distributor RPM) | 0.5° to 4° @ 650 RPM<br>5.5° to 8.5° @ 850 RPM<br>10° to 12° @ 2000 RPM |
| Advance-Vacuum (Distributor Degrees at Inches of Mercury)    | 0.5° to 3.5° @ 7"<br>7° to 10° @ 11"                                    |
| Shaft Side Play (New or Rebuilt)                             | .000" to .003"  |
| Shaft End Play (After Assembly)                              | .003" to .017"  |
| Rotation   | Clockwise   |
| Timing   | 5° BTC**  |
| Spark Plug Type  | N9Y-Champion  |
| Size   | 14MM-3/4" Reach   |
| Gap  | .035"   |
| Firing Order   | 1-8-4-3-6-5-7-2   |
| Coil   | Chrysler-Essex or Chrysler-Prestolite                                   |
| Identification Number  | 2444241 2444242   |
| Primary Resistance @70°-80°F                                 | 1.41 to 1.55 Ohms 1.65 to 1.79 Ohms                                     |
| Secondary Resistance @70°-80°F                               | 9200 to 10700 Ohms 9400 to 11700 Ohms                                   |
| Ballast Resistor   | 3656199   |
| Resistance @ 70°-80°F  | 0.5 to 0.6 Ohms (Unpotted Sect.)<br>4.75 to 5.75 Ohms (Potted Sect.)    |
| Pickup Coil  |   |
| Resistance @ 70°-80°F  | 400 to 600 Ohms   |
| Current Draw (Coil and Ballast Resistor in Circuit)          |   |
| Engine Stopped   | 3.0 amperes (Engine Warm)   |

\*Service wear tolerance should not exceed .006 inch.

\*\*Plus or minus 2-1/2°. Set at curb idle speed.






FIGURE 4 ELECTRONIC IGNITION SYSTEM WIRING DIAGRAM

Policy: Information Only

*J. D. Morton*

J. D. Morton  
Manager-Technical Service  
U.S.AUTOMOTIVE SALES & SERVICE