
Technical Service Bulletin



Of Interest
General Manager
Sales Manager
Service Manager
Parts Manager
Service Technicians

April 7, 1971

Car #: D71-21-2

Truck: 71DT-21-1

CAR AND TRUCK

All A-230 and A-833 transmissions built for 1970 and later vehicles have a new type of synchronizer rings. The new rings do not have three (3) deep slots in each bronze synchronizer ring. Rather the new design is indexed to the clutch gear by three (3) lugs on the outer diameter.

The two designs can be mixed by mistake. An old style ring can be installed with a new style synchronizer assembly. The three slots are wide enough to fit over the new wider, shorter struts. This mix results in a definite failure.

The sketch on page 2 shows the basic difference between the two designs. Also shown are the part numbers for the new synchronizer assemblies and bronze synchronizer rings. The new design synchronizer assemblies can be used in all model 833 transmissions back to the original assemblies in 1964 cars.

TRANSMISSION

Standard
Transmission
Synchronizer
Rings

POLICY: INFORMATION ONLY

J.D. monton

J. D. MORTON

Manager - Technical Services

U. S. AUTOMOTIVE SALES & SERVICE


MODELS: All
Models Equipped
With an A-230
or A-833
Transmission

P-1010-C

(THIS BULLETIN IS SUPPLIED AS TECHNICAL INFORMATION ONLY AND IS NOT AN AUTHORIZATION FOR REPAIRS)
REPRINT OF THIS MATERIAL NOT AUTHORIZED UNLESS APPROVED BY MANAGER OF SERVICE, DODGE DIVISION








SYNCHRONIZER RINGS (BRONZE)- 3515023

3410582

REAR



3410582