

Service Department

Technical Service Bulletin



Of Interest ☐ General Manager ☐ Sales Manager ☐ Service Manager ☐ Parts Manager ☐ Service Technicians

June 2, 1971

No. D71-9-5

As a result of a recent specification change, the spark plugs installed in 318 and 360 C.I.D. engines in production are N13Y. 360 Engines produced prior to this change were equipped with N10Y plugs and 318 engines with N14Y.

Engines originally equipped with the earlier plugs will give satisfactory performance on these plugs. If should, therefore, not be necessary to change from the original specification between normal servicing intervals.

When normal plug replacement is required, use the N13Y plugs.

J. D. MORTON
Manager - Technical Services
U. S. AUTOMOTIVE SALES & SERVICE

ENGINE

Spark Plug
Specification
Change

MODELS: All
1971 Passenger
Cars Equipped
With 318 and
360 C.I.D.
Engines

P-1492-C

(THIS BULLETIN IS SUPPLIED AS TECHNICAL INFORMATION ONLY AND IS NOT AN AUTHORIZATION FOR REPAIRS)
REPRINT OF THIS MATERIAL NOT AUTHORIZED UNLESS APPROVED .



COLT/CHALLENGER/CHARGER/CORONET/DART/MONACO/POLARA